

## Real Property Records

Date last updated: Friday, August 22, 2003

SDMS Document ID



1056285

## Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

[Link to property tax information for this property](#)

[Link to property sales information for this neighborhood](#)

[Link to property sales information for all Denver neighborhoods](#)

## PROPERTY INFORMATION

Property Type: Commercial

Parcel: 0225208002000

Name and Address Information

Legal Description

RODINE,ROGER A &amp; LINDA J

L 5 & S 19FT OF L 4 BLK 1  
LESSIG ADD & L 5 & S 19FT OF  
L  
4 BLK 1 CHEESMAN &  
MOFFATS ADD  
INDUSTRIAL - WAREHOUSE

390 S POPLAR ST

DENVER, CO 80224

Property Address:

Tax District

3750 YORK ST

DENV

## Assessment Information

	Actual	Assessed	Exempt	Taxable
Current Year				
Land	19200	5570		
Improvements	22000	6380		
Total	41200	11950	0	11950
Prior Year				
Land	14400	4180		
Improvements	17400	5050		
Total	31800	9230	0	9230

Style: Other

Lot Size: 4,810

Year Built: 1933

Zoning: I1

Building Sqr. Foot: 1,866

Reception No.: JT00177889

Bedrooms:

Recording Date: 12/07/00

Baths Full/Half: 0/0

Sale Price: 180000


Basement/Finished: 0/0

Mill Levy: 59.855

13-782 500 SHEETS, FILLER, 5 SQUARE  
42-381 50 SHEETS, EYE GLASS, 5 SQUARE  
42-382 100 SHEETS, EYE GLASS, 5 SQUARE  
42-383 200 SHEETS, EYE GLASS, 5 SQUARE  
National Brand  
MADE IN U.S.A.

4041

21



REPLACE WITH  
DRIVE WAY  
GRAVEL

concrete

side walk


concrete  
10' x 8'

65' x 43' = 2795

11' x 32' = 352 sq ft

56' x 17' (952)

concrete



wants  
411

90' x 39' = 3510

side walk

side walk

26' x 23' = 598

← REPLACE WITH  
DRIVE WAY GRAVEL

1540  
70' x 22'

47' x 70' = 3290

S.A.

SIDE WALK

BROWN MOLCH

11' x 70' = 770

STREET

total 6437 sq ft drive way gravel

PIN  
4041

## Property Completion Agreement

This agreement documents the completion of remedial activities performed on my property. My signature will designate that I am satisfied with the restoration of my property, and that no items are in questions, now, or at any time in the future, except those items listed below, if any.

Property ID:	4041
Property Address:	3750 York
Owner:	Roger Rodine
Phone:	303-296-8408

### Restoration Items in Question:

Item:
Item:
Item:
Item:
Item:
Item:

Additional Comments:
very pleased with restoration of property.

☒ I agree restoration is completed, except as noted

☐ I do not agree restoration is completed

Roger Rodine 10-3-03  
Owner's Signature                      Date

[Signature] 10-3-03  
Contractor's Signature                      Date



## Property Access Checklist

Property ID: <u>4041</u>	<input type="checkbox"/> WORK STARTED	ON: <u>  </u> / <u>  </u> / <u>  </u>
Property Address: <u>3750 yerik</u>	<input type="checkbox"/> WORK COMPELTED	ON: <u>  </u> / <u>  </u> / <u>  </u>

Owner: <u>Roger Rodines</u>	Renter:
Address: <u>390 s poplar way</u>	Phone:
	Fax:
	Cell/Pager:
Phone: <u>303-296-8408</u>	Additional Information:
Fax:	
Cell/Pager:	

<input checked="" type="checkbox"/> Notification Letter	Sent: <u>7/17/03</u>	By: <u>Michelle Smith</u>
<input checked="" type="checkbox"/> Access Agreement	Signed: <u>  </u> / <u>  </u> / <u>  </u>	By: <u>  </u>
<input checked="" type="checkbox"/> Restoration Agreement	Signed: <u>8/25/03</u>	By: <u>Roger Rodine</u>
<input type="checkbox"/> Topsoil Sampling (if applicable)	<u>  </u> / <u>  </u> / <u>  </u>	By: <u>  </u>
<input type="checkbox"/> Disposal Sampling (if applicable)	<u>  </u> / <u>  </u> / <u>  </u>	By: <u>  </u>
<input type="checkbox"/> Garden Sampling (if applicable)	<u>  </u> / <u>  </u> / <u>  </u>	By: <u>  </u>
<input type="checkbox"/> Utility Clearance	Called: <u>  </u> / <u>  </u> / <u>  </u>	By: <u>  </u>
<input checked="" type="checkbox"/> Video/Photos (Before)	On: <u>8/25/03</u>	By: <u>Todd Myers</u>
<input type="checkbox"/> Video/Photos (During)	On: <u>  </u> / <u>  </u> / <u>  </u>	By: <u>  </u>
<input type="checkbox"/> Video/Photos (After)	On: <u>  </u> / <u>  </u> / <u>  </u>	By: <u>  </u>
<input type="checkbox"/> Video/Photos (30-Day)	On: <u>  </u> / <u>  </u> / <u>  </u>	By: <u>  </u>
<input type="checkbox"/> Property Completion Agreement	Signed: <u>  </u> / <u>  </u> / <u>  </u>	By: <u>  </u>
<input type="checkbox"/> Final Report	Issued: <u>  </u> / <u>  </u> / <u>  </u>	By: <u>  </u>

### Air Monitoring (as applicable)

<input type="checkbox"/> Community <input type="checkbox"/> Crew	On: <u>  </u> / <u>  </u> / <u>  </u>	By: <u>  </u>
Results:		
<input type="checkbox"/> Community <input type="checkbox"/> Crew	On: <u>  </u> / <u>  </u> / <u>  </u>	By: <u>  </u>
Results:		
<input type="checkbox"/> Community <input type="checkbox"/> Crew	On: <u>  </u> / <u>  </u> / <u>  </u>	By: <u>  </u>
Results:		

**Permission to Access Property**  
**VBI-70**

**Property Address:** 3750

**Owner:** Roger Rodine

**Date:** 8-22-03

**Any special Instructions?**

Owner grants Access to property to use  
psrt of property for our trucks to excavate  
3730 york st.

303-256-8408

**Owner Signature:** Roger Rodine

**Contractor Signature:** [Signature]

# FINAL PROPERTY MEASUREMENTS

DATE 10-3-03

PIN 4041

red  
MULCH 737

Drive  
ROCK ~~6600~~ NA

DIRT ONLY NA

DRIVEWAY GRAVEL 6600

11 x 67 mulch 67  
21

167

678

737

Drive gravel

1679 73 x 23

736 46 x 16

21 7 x 3

1230 30 x 41

297 11 x 27

2394 57 x 42

177 59 x 3

66 3 x 22

6600



Project Resources Inc.

## Restoration Agreement

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID:	4041
Property Address:	3750 York
Owner:	Roger Rodines
Phone:	303-296-8408

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

### Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

Item:	Brick + Iron pile in back
Item:	Cars in back lot
Item:	
Item:	
Item:	
Item:	
Item:	
Item:	



**Items To Be Removed By Contractor During Remediation And Not Replaced**  
(Use additional sheets as necessary)

Item:	Concrete squares in back yard
Item:	a. trees in back yard
Item:	circle of brick + concrete
Item:	
Item:	
Item:	
Item:	
Item:	
Item:	
Item:	
Item:	
Item:	
Item:	
Item:	





Project Resources Inc.

**Items To Be Removed By Contractor During Remediation And Replaced**  
(Use additional sheets as necessary)

Item: <i>NONE</i>
Item:
Item:
Item:
Item:
Item:
Item:
Item:
Item:
Item:
Item:
Item:
Item:
Item:
Item:



Project Resources Inc.

**Landscape Inventory**  
(Use additional sheets as necessary)

Item	Quantity	Unit	Condition/Type/Species
Evacuated area of yard	<u>6852</u> 6437	Square feet	
Number of trees > 2 inch trunk diameter	0	Each	
Number of trees ≤ 2 inch trunk diameter	0	Each	
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc.  Attach a sketch of the sprinkler layout.	None	Each	
Number of and size of each garden/ flower bed area.  Attach a sketch of relative sizes and locations.	None	Each Square Feet	



Item	Quantity	Unit	Condition/Type/Species
<p>Agreed upon value of plant materials <u>not to be replaced</u> by contractor.</p> <p>Note this value will be used to issue a replacement certificate to the property owner.</p>	NONE	\$	
<p>Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed.</p> <p>Include a sketch of where each plant will be placed by the contractor.</p>	NONE	Each	
<p>Agreed upon area of property to be replaced with grass sod.</p> <p>Include a sketch of the area(s) to be replaced with grass sod.</p>	5657	SF	
<p>Area of City or County property to be landscaped per their requirements.</p> <p>Include a sketch of the area (s)</p>	770	SF	



Project Resources Inc.

**Additional Comments / Instructions:**

? About crushed Asphalt

☐ Check the box if Owner does not want PRI to document interior foundation walls and possible pre-existing damage. By checking this box PRI is not responsible for any damage done to the interior of house, including foundation cracks or fissures.

☒ I agree

☐ I do not agree

☒ I agree

☐ I do not agree

Roger Rodine 8-25-03  
Owner's Signature Date

[Signature] 8-25-03  
Contractor's Signature Date



Address: 3750 York St.		Date: 8/8/2005	
Owner: Roger	Rodines	Telephone #:	(303) 296-8408

Plot Plan:

see attached

Prop. ID# 4041<sup>st</sup>

1530 sq ft<sup>2</sup>


	Exterior Walls				Doors/Trim			
	Material	deteriorated Area	Peel/Chip	XRF (Lead)	Material	deteriorated Area	Peel/Chip	XRF (Lead)
North	brick/wood	397.00		3+-1.3				
South	brick/wood	361.31		3+-1.3				
East	brick/wood	258.67		3+-1.3				
West	brick/wood	204.39		3+-1.3				
	Total	1221.37			Total	0.00		

	Window Trim/Fascia/Soffit				Patios/Decks/Porches			
	Material	deteriorated Area	Peel/Chip	XRF (Lead)	Material	deteriorated Area	Peel/Chip	XRF (Lead)
North	wood	70.00		3+-1.3				
South	wood	17.50		3+-1.3				
East	wood	49.00		3+-1.3				
West	wood	25.88		3+-1.3				
	Total	162.38			Total	0.00		



  

	Metal Trim/Gutters/Downspouts				Misc Structures/Garage/Fences			
	Material	deteriorated Area	Peel/Chip	XRF (Lead)	Material	deteriorated Area	Peel/Chip	XRF (Lead)
North								
South								
East								
West					wood/brick	21.22		3+-1.3
	Total	0.00			Total	21.22		



$$(20+12)(22+12) - (20 \times 22)$$

$$(32)(34) - 440 = 1088 - 440 = 648 \text{ sq ft}$$



3750 York St





# Color Photo(s)

The following pages  
contain color that does  
not appear in the  
scanned images.

To view the actual images, contact  
the Region VIII Records Center at  
(303) 312-6473.

2



4





1




3









1)	4041-001-DWC	0910	6/6/06
2)	4041-002-DWC	0915	6/6/06
3)	4041-001-SCC	0920	6/6/06
4)	4041-002-SCC	0925	6/6/06
5)			
6)			

# Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862  
(303) 425-6021

Client Sample ID: 4041-001-DWC

Client Project ID: 213001.01

Date Collected: 6/6/06

Date Received: 6/8/06

Lab Work Order: 06-3650

Lab Sample ID: 06-3650-05

Sample Matrix: Wipe

## METALS

Method: SW6010

Prep Method: SW6010

Date Prepared: 6/9/06

Lab File ID: 061206PM

Dilution Factor: 1

Date Analyzed: 6/13/06

Method Blank: MB-10113

Lab Fraction ID: 06-3650-05A

Analytes	CAS Number	Result	LQL	Units
Lead	7439-92-1	U	4.0	µg/WIPE

MB

Analyst



Approved

**Qualifiers:** B - Analyte detected in the associated Method Blank, value not subtracted from result  
E - Extrapolated value. Value exceeds calibration range  
H - Sample analysis exceeded analytical holding time  
J - Indicates an estimated value when the compound is detected, but is below the LQL  
S - Spike Recovery outside accepted limits  
U - Compound analyzed for but not detected  
X - See case narrative  
\* - Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

**Definitions:** NA - Not Applicable  
LQL - Lower Quantitation Limit  
Surr - Surrogate

Print Date: 6/19/06

# Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862  
(303) 425-6021

Client Sample ID: 4041-002-DWC  
Client Project ID: 213001.01  
Date Collected: 6/6/06  
Date Received: 6/8/06

Lab Work Order: 06-3650  
Lab Sample ID: 06-3650-06  
Sample Matrix: Wipe

## METALS

Method: SW6010

Prep Method: SW6010

Date Prepared: 6/9/06  
Date Analyzed: 6/13/06

Lab File ID: 061206PM  
Method Blank: MB-10113

Dilution Factor: 1  
Lab Fraction ID: 06-3650-06A

Analytes	CAS Number	Result	LQL	Units
Lead	7439-92-1	U	4.0	µg/WIPE

MB

Analyst

CW

Approved

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result  
E - Extrapolated value. Value exceeds calibration range  
H - Sample analysis exceeded analytical holding time  
J - Indicates an estimated value when the compound is detected, but is below the LQL  
S - Spike Recovery outside accepted limits  
U - Compound analyzed for but not detected  
X - See case narrative  
\* - Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Definitions: NA - Not Applicable  
LQL - Lower Quantitation Limit  
Surr - Surrogate

Print Date: 6/19/06

# Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862  
(303) 425-6021

Client Sample ID: 4041-001-SCC  
Client Project ID: 213001.01  
Date Collected: 6/6/06  
Date Received: 6/8/06

Lab Work Order: 06-3650  
Lab Sample ID: 06-3650-07  
Sample Matrix: Soil

## METALS

Method: SW6010

Prep Method: SW3050

Date Prepared: 6/12/06  
Date Analyzed: 6/16/06

Lab File ID: 061606PM  
Method Blank: MB-10126

Dilution Factor: 1  
Lab Fraction ID: 06-3650-07A

Analytes	CAS Number	Result	LQL	Units
Lead	7439-92-1	44	5.6	mg/Kg

*MB*

Analyst

*[Signature]*

Approved

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result  
E - Extrapolated value. Value exceeds calibration range  
H - Sample analysis exceeded analytical holding time  
J - Indicates an estimated value when the compound is detected, but is below the LQL  
S - Spike Recovery outside accepted limits  
U - Compound analyzed for but not detected  
X - See case narrative  
\* - Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Definitions: NA - Not Applicable  
LQL - Lower Quantitation Limit  
Surr - Surrogate

Print Date: 6/19/06



# Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862  
(303) 425-6021

Client Sample ID: 4041-002-SCC  
Client Project ID: 213001.01  
Date Collected: 6/6/06  
Date Received: 6/8/06

Lab Work Order: 06-3650  
Lab Sample ID: 06-3650-08  
Sample Matrix: Soil

## METALS

Method: SW6010

Prep Method: SW3050

Date Prepared: 6/12/06  
Date Analyzed: 6/17/06

Lab File ID: 061606PM  
Method Blank: MB-10126

Dilution Factor: 1  
Lab Fraction ID: 06-3650-08A

Analytes	CAS Number	Result	LQL	Units
Lead	7439-92-1	110	5.7	mg/Kg

MB

Analyst

UWA

Approved

**Qualifiers:** B - Analyte detected in the associated Method Blank, value not subtracted from result  
E - Extrapolated value. Value exceeds calibration range  
H - Sample analysis exceeded analytical holding time  
J - Indicates an estimated value when the compound is detected, but is below the LQL  
S - Spike Recovery outside accepted limits  
U - Compound analyzed for but not detected  
X - See case narrative  
\* - Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

**Definitions:** NA - Not Applicable  
LQL - Lower Quantitation Limit  
Surr - Surrogate

Print Date: 6/19/06

This spreadsheet performs screening level calculations to estimate the effect of peeling leaded paint on the average concentration of lead in yard soil  
**3750 York St.**

INPUTS			House	Garage
<b>General</b>	Variable	Units		
	Mixing depth in yard	cm	2.54	2.54
	Mixing depth in yard	inches	1	1
	Soil density	g/cm3	2.5	2.5
	RBC in soil	mg/kg	400	400
	Bkg in clean fill	mg/kg	50	50
<b>House-specific</b>			<b>Small</b>	<b>Small</b>
	Area of the exposure unit	m2	74.69404	60.20117
	Area of the exposure unit	ft2	804	648
	Concentration of lead in paint	mg/cm2	3	3
	Area of peeling paint	m2	128.5546	1.9714025
	Area of peeling paint	ft2	1383.75	21.22
COMPUTATIONS				
	Mass of lead from paint	mg	3.9E+06	5.9E+04
	Volume of soil	cm3	1.9E+06	1.5E+06
	Mass of soil	kg	4.7E+03	3.8E+03
	Incremental concentration	mg/kg	813.1	15.5
	Maximum acceptable area of peeling leaded paint (m2)		55.3	44.6
	Maximum acceptable area of peeling leaded paint (ft2)		595.4	479.9
DECISION			Not OK	OK

4041

Address: 3750 York St.		Date: 8/8/2005	
Owner: Roger	Rodines	Telephone #:	( 303) 296-8408

Plot Plan:




Prop. ID#  
4041

see attached

	Exterior Walls				Doors/Trim			
	Material	deteriorated Area	Peel/Chip	XRF (Lead)	Material	deteriorated Area	Peel/Chip	XRF (Lead)
North	brick/wood	397.00		3+-1.3				
South	brick/wood	361.31		3+-1.3				
East	brick/wood	258.67		3+-1.3				
West	brick/wood	204.39		3+-1.3				
	Total	1221.37			Total	0.00		

	Window Trim/Fascia/Soffit				Patios/Decks/Porches			
	Material	deteriorated Area	Peel/Chip	XRF (Lead)	Material	deteriorated Area	Peel/Chip	XRF (Lead)
North	wood	70.00		3+-1.3				
South	wood	17.50		3+-1.3				
East	wood	49.00		3+-1.3				
West	wood	25.88		3+-1.3				
	Total	162.38			Total	0.00		

	Metal Trim/Gutters/Downspouts				Misc Structures/Garage/Fences			
	Material	deteriorated Area	Peel/Chip	XRF (Lead)	Material	deteriorated Area	Peel/Chip	XRF (Lead)
North								
South								
East								
West					wood/brick	21.22		3+-1.3
	Total	0.00			Total	21.22		



3750 York St

3750 York St.		Structure:		House							
8/8/2005		Direction:		West							
WH & CM											
11:45 a.m.											
Drawing Number	Photo Number	Painted Surface	Material	Color	Total Area of Element (units ft^2)	Percent Deteriorated	Deteriorated Area (units ft^2)	XRF #	XRF Value	pos/neg	Notes
1	1	Walls/ Window Frames	Brick/Wood	white	204.39	100%	204.39	71	3.0 +- 1.3	Pos.	
2	2	Soffit	wood	white	49	50%	24.50	see 71	3.0 +- 1.3	Pos.	
3	3	Basement Window Frame	wood	white	1.38	100%	1.38	72	2.0 +- 0.7	Pos	
3750 York St.		Structure:		House							
8/8/2005		Direction:		South							
WH & CM											
11:45a.m.											
Drawing Number	Photo Number	Painted Surface	Material	Color	Total Area of Element (units ft^2)	Percent Deteriorated	Deteriorated Area (units ft^2)	XRF #	XRF Value	pos/neg	Notes
		Walls/Window Frames/ Door Frame	Wood	white	361.31	100%	361.31	see 71	3.0 +- 1.3	Pos	
4	4	Frame	Wood	white	361.31	100%	361.31	see 71	3.0 +- 1.3	Pos	
5	5	Soffit	Wood	white	70	25%	17.50	see 71	3.0 +- 1.3	Pos.	
3750 York St.		Structure:		House							
8/8/2005		Direction:		East							
WH & CM											
11:45 a.m.											
Drawing Number	Photo Number	Painted Surface	Material	Color	Total Area of Element (units ft^2)	Percent Deteriorated	Deteriorated Area (units ft^2)	XRF #	XRF Value	pos/neg	Notes
		Walls/Window Frames	Brick/Wood	white	258.67	100%	258.67	see 71	3.0+- 1.3	Pos.	
6	6	Frames	Brick/Wood	white	258.67	100%	258.67	see 71	3.0+- 1.3	Pos.	
7	7	Soffit	Wood	white	49	100%	49.00	see 71	3.0 +- 1.3	Pos.	
3421 Josephine St.		Structure:		House							
8/8/2005		Direction:		North							
WH & CM											
11:45 a.m.											
Drawing Number	Photo Number	Painted Surface	Material	Color	Total Area of Element (units ft^2)	Percent Deteriorated	Deteriorated Area (units ft^2)	XRF #	XRF Value	pos/neg	Notes
		Walls/Window Frames	Brick/Wood	white	397	100%	397.00	see 71	3.0 +- 1.3	Pos.	
8	8	Frames	Brick/Wood	white	397	100%	397.00	see 71	3.0 +- 1.3	Pos.	
9	9	Soffit	Wood	white	70	100%	70.00	see 71	3.0 +- 1.3	Pos.	
3750 York St.		Structure:		Garage							
8/8/2005		Direction:		West							
WH & CM											
11:45 a.m.											
Drawing Number	Photo Number	Painted Surface	Material	Color	Total Area of Element (units ft^2)	Percent Deteriorated	Deteriorated Area (units ft^2)	XRF #	XRF Value	pos/neg	Notes
		Garage Car Door, door frame, soffit	Wood	white			1.00	73	11 +- 2.9	Pos	
10	10	door frame, soffit	Wood	white			1.00	73	11 +- 2.9	Pos	
11	11	West Walls	Brick	white		100%	20.22	See 71	3.0 +- 1.3	Pos.	
OWNER WANTS TO DEMOLISH BUILDING											

**TARGET SHEET**  
**EPA REGION VIII**  
**SUPERFUND DOCUMENT MANAGEMENT SYSTEM**

DOCUMENT NUMBER: 1056285

SITE NAME: VASQUEZ BOULEVARD AND I-70

DOCUMENT DATE: 10/03/2003

**DOCUMENT NOT SCANNED**

Due to one of the following reasons:

- ☒ PHOTOGRAPHS
- ☐ 3-DIMENSIONAL
- ☐ OVERSIZED
- ☒ AUDIO/VISUAL
- ☐ PERMANENTLY BOUND DOCUMENTS
- ☐ POOR LEGIBILITY
- ☐ OTHER
- ☐ NOT AVAILABLE
- ☐ TYPES OF DOCUMENTS NOT TO BE SCANNED  
(Data Packages, Data Validation, Sampling Data, CBI, Chain of Custody)

**DOCUMENT DESCRIPTION:**

1 - DVD OF PROPERTY VIDEO, PROPERTY #4041  
1 - PROPERTY DATA CD  
1 - PROPERTY PHOTO CD